

ommendations, such as wire colours and pin numbers, should be tested with a multimeter or test light for the required signal prior to using .



FITMENT GUIDE

Make	Model	LINX Controller (ECU) Location	USB extension cable 7450118 needed?	Power Wiring Harness extension needed?	Fuse Taps 7450119 (pack of 2) needed?	A-Pillar bracket part number	High beam pickup	Low beam pickup	Accessory (ACC) Pickup	Reverse pickup	Recommended Air Compressor location	Air Compressor Bracket part number	Recommended LINX TPMS Comms Box 7450116 location	Notes
Chevrolet / Holden	Colorado	Under Driver Seat	No	Yes	Yes	7450106	P/side H/light white wire Pin #9	P/side H/light yellow wire Pin #7	D/side Incab Fuse Box 15A top right	D/side kick panel grey plug green/white trace wire	Under Rear Seat	3501010	In headliner or on rear glass	
Dodge	Ram 1500 2018+	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450115	P/side H/light white/green trace Pin #7	P/side H/light white/blue trace Pin #5	Engine Bay Fuse Box Pin 93	Engine Bay Fuse Box Fuse 28	Under Rear Seat	3501010	In headliner or on rear glass	
Ford	Ranger PXI	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450111	P/side H/light grey/brown wire	Instrument Panel Fuse Box Fuse 74	Instrument Panel Fuse Box Fuse 76	D/side kick panel red/white trace wire bottom plug	Behind Rear Seat	3501010	In headliner next to light	
Ford	Ranger PXII	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450111	Headlight grey/brown	Headlight brown/blue	Engine Fuse Box Pin 20	Taillight red/yellow trace wire	Behind Rear Seat	3540320	In headliner next to light	
Ford	Ranger PXIII Raptor	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450111	Headlight grey/brown	Headlight brown/blue	Engine Fuse Box, Fuse 3	P/side Rear foot trim, Grey/Orange wire	Behind Rear Seat	3540320	In headliner next to light	Firewall access top left of Passenger footwell
GWM	Cannon 2021+	Under Rear Seat Behin Rear Seat	Yes	Yes	TBC	TBC	P/Side H/Light Green/Yellow	TBA	TBA	TBA	Under Rear Seat	3501010	In headliner next to light or in Centre Console	NOTE- negatively switched. Code IC004
Isuzu	D-Max 2012-2020	Behind Rear Seat	Yes	Yes	Yes	7450106	P/side H/light Red/yellow trace	P/side H/light red/black trace	Engine Bay Fuse Box A/C 10 amp Fuse	Taillight red/brown trace	Behind Rear Seat	3501010	In headliner or on rear glass	
Isuzu	D-Max 2021+	Behind Rear Seat	Yes	Yes	Yes	7450106	TBA	ТВА	TBA	ТВА	Behind Rear Seat	3501010	In headliner or on rear glass	
Jeep	JK Wrangler	Under Driver Seat	No	Yes	Yes	7450112	H/light orange/red wire	H/light Violet/White wire	Engine Bay Fuse Box	Tailight Violet/Black wire	Under Passenger Seat	3550210	Under/ behind centre console	Firewall access above Passenger door hinge
Jeep	JL Wrangler	Under Driver Seat	No	Yes	Yes	7450117	P/side H/light White/green trace wire	P/side H/light White/blue trace wire	Engine Fuse Box Fuse F52	Engine Fuse Box Fuse F11 / Right Tailight White/Violet	Under Passenger Seat	3550220	In headliner	
Jeep	JT Gladiator	Under Rear Seat	Yes	Yes	Yes	7450117	P/side H/light white/green trace wire	P/side H/light white/blue trace wire	Engine Bay Fuse Box Fuse 11	Engine Bay Fuse Box Fuse 111	Under Passenger Seat	3550220	In headliner	
Mazda	BT50 2011-2020	Behind Passenger Rear Seat	Yes	Yes	Yes	7450111	TBC	Engine Fuse Box Fuse 17	Engine Fuse Box Fuse 4	TBC	Behind Rear Seat	3540320	In headliner or on rear glass	
Mazda	BT50 2021+	Behind Passenger Rear Seat	Yes	Yes	TBC	7450106	P/side h/light pink wire	P/side H/light red wire	D/side Incab fuse box 10amp (USB fuse)	P/side tail light car harness red wire	Behind Rear Seat	3540320	In headliner or on rear glass	
Mitsubishi	Triton MQ/MR	Behind Rear Seat	Yes	Yes	Yes	7450106	Engine Fuse Box Fuse F3/F4	Engine Fuse Box Fuse F1/2	Instrument Panel Fuse Box Pin 2	Instrument Panel Fuse Box Pin 21	Behind Rear Seat	3501010	In headliner or on rear glass	
Mitsubishi	Pajero Sport	Under Passenger Seat	Yes	Yes	Yes	7450111	Engine Fuse Box Fuse 14	Engine Fuse Box Fuse 16	Passenger Side Fuse Box Fuse 2	Passenger Side Fuse Box Fuse 21	TBC	3501010	In headliner	
Nissan	Navara D40 2005 - 2015	Under Driver Seat	No	No	TBC	7450106								
Nissan	Navara NP300 2015 - 2020	Behind Rear Seat	Yes	Yes	Yes	7450114	P/side H/light green wire Pin#2	P/side H/light Pink wire Pin #1	P/side incab Fuse Box. bottom left Fuse	Taillight blue wire	Behind Rear Seat	3501010	In headliner or on rear glass	NOTE- negatively switched. Code IC004
Nissan	Navara NP300 2021+	Behind Rear Seat	Yes	Yes	TBC	7450111	D/side H/light yellow/red wire	TBC	TBC	TBC	Behind Rear Seat	3501010	In headliner or on rear glass	NOTE- negatively switched. Code IC004 A-Pillar bracket requires slight bending
Nissan	Patrol Y62 S5	Under Dash Footwells	No	Yes	Yes	7450111	D/side H/light red wire	D/side H/light white wire	D/side incab fusebox 15 amp (power socket)	P/side kick panel red/yellow trace wire	P/side behind Rear panel	3527070	In headliner	
Suzuki	Jimny 2018+	Under Passenger Seat	Yes	Yes	Yes	7450114	Engine Fuse Box Fuse 32/33	Passenger Compartment Fuse Box Fuse 28	Instrument Panel Fuse Box Pin 33	Engine Bay Fuse Box Pin 18	Under Driver Seat	3501010	Behind centre console or in headliner	
Toyota	Landcruiser 200	Under Passenger Seat	No	Yes	Yes	7450110	P/side H/light Pin 4 blk plug	H/light Pin1 blk plug	Engine Bay Fusebox (ENG-IG2 NO.2)	P/side foot trim main harness thin dark blue wire	D/side Rear panel	3515130	In headliner or on rear glass	
Toyota	Landcruiser 79	Behind Rear Seat or under Driver Seat	No	Yes	Yes	7450106	P/side H/light red/yellow trace wire	P/side H/light blue/white trace wire	Passenger side incab Fusebox	D/side foot trim red/black wire	under passenger Seat	3512080	On rear window glass	
Toyota	Landcruiser 100	Under Passenger Seat	No	Yes	Yes	7450106	Engine Fuse Box Fuse 16/17	Engine Fuse Box Fuse 19	Engine Fuse Box Pin 22	P/side foot trim red/black trace wire	Engine Bay P/side firewall	3501010	In headliner or under centre console	
Toyota	Landcruiser 80	Under Passenger Seat	No	Yes	Yes	7450106	Headlight Red Wire	Headlight Yellow Wire	Engine Fuse Box Fuse 19	P/side foot trim thick red/black trace wire	Under Drivers Seat	3501010	In headliner or under centre console	
Toyota	Prado 150	Under Passenger Seat	No	Yes	Yes	7450106	Indicator stalk light green wire Pin #17	Indicator stalk light blue wire Pin #12	Drivers footwell Fuse Box Pin 2	P/side foot trim main harness thick red wire	Behind Passenger Rear boot trim	3521080	In headliner or under centre console	NOTE- negatively switched code IC005
Toyota	Hilux 2015+	Behind Glove Box	No	Yes	Yes	7450106	P/side H/light thick white wire	P/side H/light red wire	P/side kick panel Fuse Box ign #2	P/side foot trim main harness red thick wire	Behind Rear Seat	3514111	Behind glovebox or left side cavity	
Toyota	Hilux 2004 - 2015	Under Passenger seat	No	No	Yes	ТВС	P/side H/light black/yellow trace wire	P/side H/light black/white trace wire	Incab D/side fuse box ACC FUSE 7.5A	P/side rear foot trim red/white trace wire	Engine Bay	N/A	In headliner or under centre console	
Toyota	FJ Cruiser	Under Driver Seat	No	Yes	Yes	7450115	Engine Bay Fuse Box Fuse 10	Engine Bay Fuse Box Fuse 8	Instrument Panel Fuse Box Fuse 35	P/side kick panel red/yellow trace wire	Engine Bay D/side	3501010	In headliner or under centre console	
Toyota	Fortuner	D/side kick panel wall	No	Yes	Yes	7450106	P/side H/light white wire Pin #2	P/side H/light red wire Pin #3	P/side kick panel Fuse Box ign #2	P/side foot trim red thick wire	TBC	3501010	In headliner or under centre console	
Toyota	Tacoma	Under Rear Seat	Yes	Yes	Yes	7450115	Engine Fuse Box Fuse 17	Engine Fuse Box Fuse 15	Engine Fuse Box Fuse 5	Trailer harness	Under Rear Seat	3523010	In headliner or on rear glass	
Toyota	4Runner	Under Rear Seat	Yes	Yes	Yes	TBC	Engine Fuse Box Fuse 16/17	Engine Fuse Box Fuse 37/38	Engine Fuse Box Fuse 2	D/side foot trim red/yellow trace wire	Engine Bay	N/A	In headliner or under centre console	
Volkswagen	VW Amarok	Behind Rear Seat	Yes	Yes	Yes	7450111	P/side H/light Pin #8	P/side H/light Pin #6	Instrument Panel Fuse Box Fuse 54/59	P/side taillight black/blue trace	Behind Rear Seat	3501010	In headliner or on rear glass	