

# FITMENT GUIDE

Make	Model	LINX Controller (ECU) Location	USB extension cable 7450118 needed?	Power Wiring Harness extension needed?	Fuse Taps 7450119 (pack of 2) needed?	A-Pillar bracket part number	Night Hawk Hi-Beam Adapter Part Number	High beam pickup	Low beam pickup	Accessory (ACC) Pickup	Reverse pickup	Recommended Air Compressor location	Air Compressor Bracket part number	Recommended LINX TPMS Comms Box 7450116 location	Notes	
Chevrolet / Holden	Colorado	Under Driver Seat	No	Yes	Yes	7450106	NHWA02H23	P/side H/light white wire Pin #9	P/side H/light yellow wire Pin #7	D/side Incab Fuse Box 15A top right	D/side kick panel grey plug green/white trace wire	Under Rear Seat	3501010	In headliner or on rear glass		
Chevrolet / Holden	Silverado 2019+	Under Driver Seat	Yes	Yes	TBA	TBA	TBA	P/side H/light white wire Pin #4	TBA	TBA	TBA					
Dodge	Ram 1500 2018+	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450115	TBA	P/side H/light white/green trace Pin #7	P/side H/light white/blue trace Pin #5	Engine Bay Fuse Box Pin 93	Engine Bay Fuse Box Fuse 28	Under Rear Seat	3501010	In headliner or on rear glass		
Ford	Ranger PXI	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450111	TBA	P/side H/light grey/brown wire	Instrument Panel Fuse Box Fuse 74	Instrument Panel Fuse Box Fuse 76	D/side kick panel red/white trace wire bottom plug	Behind Rear Seat	3501010	In headliner next to light		
Ford	Ranger PXII	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450111	NHWA02H31 (all models)	Headlight grey/brown	Headlight brown/blue	Engine Fuse Box Pin 20	Taillight red/yellow trace wire	Behind Rear Seat	3540320	In headliner next to light		
Ford	Ranger PXIII Raptor	Under Rear Seat, Passenger side	Yes	Yes	Yes	7450111	NHWA02H31 (all models)	Headlight grey/brown	Headlight brown/blue	Engine Fuse Box, Fuse 3	P/side Rear foot trim, Grey/Orange wire	Behind Rear Seat	3540320	In headliner next to light	Firewall access top left of Passenger footwell	
GWM	Cannon 2021+	Under Rear Seat Behind Rear Seat	Yes	Yes	TBA	TBA	TBA	P/Side H/Light Green/Yellow	TBA	TBA	TBA	Under Rear Seat	3501010	In headliner next to light or in Centre Console	NOTE- negatively switched. Code IC004	
Isuzu	D-Max 2012-2020	Behind Rear Seat	Yes	Yes	Yes	7450106	NHWA02H24 (LED h/light only)	P/side H/light Red/yellow trace	P/side H/light red/black trace	Engine Bay Fuse Box A/C 10 amp Fuse	Taillight red/brown trace	Behind Rear Seat	3501010	In headliner or on rear glass		
Isuzu	D-Max 2021+	Behind Rear Seat	Yes	Yes	Yes	7450106	NHWA02H25 (LED h/light only)	P/side H/light Pink wire	P/side H/light Red wire	D/side Incab Fuse Box 10A IG1	Taillight red/yellow trace wire	Behind Rear Seat	3501010	In headliner or on rear glass		
Isuzu	M-UX 2021+	Under Driver Seat Under Passenger Seat	No	Yes	TBA	7450115	NHWA02H24 (LED h/light only)	TBA	TBA	TBA						
Jeep	JK Wrangler	Under Driver Seat	No	Yes	Yes	7450112	TBA	H/light orange/red wire	H/light Violet/White wire	Engine Bay Fuse Box	Taillight Violet/Black wire	Under Passenger Seat	3550210	Under/ behind centre console	Firewall access above Passenger door hinge	
Jeep	JL Wrangler	Under Driver Seat	No	Yes	Yes	7450117	NHWA02H36	P/side H/light White/green trace wire	P/side H/light White/blue trace wire	Engine Fuse Box Fuse F52	Engine Fuse Box Fuse F11 / Right Taillight White/Violet	Under Passenger Seat	3550220	In headliner		
Jeep	JT Gladiator	Under Rear Seat	Yes	Yes	Yes	7450117	NHWA02H36	P/side H/light white/green trace wire	P/side H/light white/blue trace wire	Engine Bay Fuse Box Fuse 11	Engine Bay Fuse Box Fuse 111	Under Passenger Seat	3550220	In headliner		
Mazda	BT50 2011-2020	Behind Passenger Rear Seat	Yes	Yes	Yes	7450111	TBA	TBC	Engine Fuse Box Fuse 17	Engine Fuse Box Fuse 4	TBC	Behind Rear Seat	3540320	In headliner or on rear glass		
Mazda	BT50 2021+	Behind Passenger Rear Seat	Yes	Yes	TBC	7450106	NHWA02H25	P/side h/light pink wire	P/side H/light red wire	D/side Incab fuse box 10amp (USB fuse)	P/side tail light car harness red wire	Behind Rear Seat	3540320	In headliner or on rear glass		
Mitsubishi	Triton MQ/MR	Behind Rear Seat	Yes	Yes	Yes	7450106	NHWA02H32 (MQ HID's) NHWA02H33 (MR LED's)	Engine Fuse Box Fuse F3/F4	Engine Fuse Box Fuse F1/2	Instrument Panel Fuse Box Pin 2	Instrument Panel Fuse Box Pin 21	Behind Rear Seat	3501010	In headliner or on rear glass		
Mitsubishi	Pajero Sport	Under Passenger Seat	Yes	Yes	Yes	7450111	NHWA02H34 (15-19 LED) NHWA02H35 (19+ LED)	Engine Fuse Box Fuse 14	Engine Fuse Box Fuse 16	Passenger Side Fuse Box Fuse 2	Passenger Side Fuse Box Fuse 21	TBC	3501010	In headliner		
Nissan	Navara D40 2005 - 2015	Under Driver Seat	No	No	TBA	7450106	TBA									
Nissan	Navara NP300 2015 - 2020	Behind Rear Seat	Yes	Yes	Yes	7450114	NHWA02H29 (LED h/light only)	P/side H/light green wire Pin#2	P/side H/light Pink wire Pin #1	P/side incab Fuse Box, bottom left Fuse	Taillight blue wire	Behind Rear Seat	3501010	In headliner or on rear glass	NOTE- negatively switched. Code IC004	
Nissan	Navara NP300 2021+	Behind Rear Seat	Yes	Yes	Yes	7450111	NHWA02H29 (LED h/light only)	P/side H/light grey wire pin 2	P/side H/light grey wire pin 1	incab Behind glovebox 10amp (ignition power)	Taillight blue wire	Behind Rear Seat	3501010	In headliner or on rear glass	NOTE- negatively switched. Code IC004 A-Pillar bracket requires slight bending	
Nissan	Patrol Y62 S5	Under Dash Footwells	No	Yes	Yes	7450111	NHWA02H30 (Series 5+)	D/side H/light red wire	D/side H/light white wire	D/side incab fusebox 15 amp (power socket)	P/side kick panel red/yellow trace wire	P/side behind Rear panel	3527070	In headliner		
Suzuki	Jimny 2018+	Under Passenger Seat	Yes	Yes	Yes	7450114	NHWA02H24 (LED h/light only)	Engine Fuse Box Fuse 32/33	Passenger Compartment Fuse Box Fuse 28	Instrument Panel Fuse Box Pin 33	Engine Bay Fuse Box Pin 18	Under Driver Seat	3501010	Behind centre console or in headliner		
Toyota	Landcruiser 200	Under Passenger Seat	No	Yes	Yes	7450110	NHWA02H28 (2016+)	P/side H/light Pin 4 blk plug	H/light Pin1 blk plug	Engine Bay Fusebox (ENG-IG2 NO.2)	P/side foot trim main harness thin dark blue wire	D/side Rear panel	3515130	In headliner or on rear glass		
Toyota	Landcruiser 79	Behind Rear Seat or under Driver Seat	No	Yes	Yes	7450106	TBA	P/side H/light red/yellow trace wire	P/side H/light blue/white trace wire	Passenger side incab Fusebox	D/side foot trim red/black wire	under passenger Seat	3512080	On rear window glass		
Toyota	Landcruiser 100	Under Passenger Seat	No	Yes	Yes	7450106	TBA	Engine Fuse Box Fuse 16/17	Engine Fuse Box Fuse 19	Engine Fuse Box Pin 22	P/side foot trim red/black trace wire	Engine Bay P/side firewall	3501010	In headliner or under centre console		
Toyota	Landcruiser 80	Under Passenger Seat	No	Yes	Yes	7450106	TBA	Headlight Red Wire	Headlight Yellow Wire	Engine Fuse Box Fuse 19	P/side foot trim thick red/black trace wire	Under Drivers Seat	3501010	In headliner or under centre console		
Toyota	Prado 150	Under Passenger Seat	No	Yes	Yes	7450106	TBA	Indicator stalk light green wire Pin #17	Indicator stalk light blue wire Pin #12	Drivers footwell Fuse Box Pin 2	P/side foot trim main harness thick red wire	Behind Passenger Rear boot trim	3521080	In headliner or under centre console	NOTE- negatively switched code IC005	
Toyota	Hilux 2015+	Behind Glove Box	No	Yes	Yes	7450106	NHWA02H26 (Bi-LED h/lights only)	P/side H/light thick white wire	P/side H/light red wire	P/side kick panel Fuse Box ign #2	P/side foot trim main harness red thick wire	Behind Rear Seat	3514111	Behind glovebox or left side cavity		
Toyota	Hilux 2004 - 2015	Under Passenger seat	No	No	Yes	TBA	TBA	P/side H/light black/yellow trace wire	P/side H/light black/white trace wire	Incab D/side fuse box ACC FUSE 7.5A	P/side rear foot trim red/white trace wire	Engine Bay	N/A	In headliner or under centre console		
Toyota	FJ Cruiser	Under Driver Seat	No	Yes	Yes	7450115	TBA	Engine Bay Fuse Box Fuse 10	Engine Bay Fuse Box Fuse 8	Instrument Panel Fuse Box Fuse 35	P/side kick panel red/yellow trace wire	Engine Bay D/side	3501010	In headliner or under centre console		
Toyota	Fortuner	D/side kick panel wall	No	Yes	Yes	7450106	NHWA02H24 (pre 08/20) NHWA02H27 (post 08/20)	P/side H/light white wire Pin #2	P/side H/light red wire Pin #3	P/side kick panel Fuse Box ign #2	P/side foot trim red thick wire	TBC	3501010	In headliner or under centre console		
Toyota	Tacoma	Under Rear Seat	Yes	Yes	Yes	7450115	TBA	Engine Fuse Box Fuse 17	Engine Fuse Box Fuse 15	Engine Fuse Box Fuse 5	Trailer harness	Under Rear Seat	3523010	In headliner or on rear glass		
Toyota	4Runner	Under Rear Seat	Yes	Yes	Yes	TBA	TBA	Engine Fuse Box Fuse 16/17	Engine Fuse Box Fuse 37/38	Engine Fuse Box Fuse 2	D/side foot trim red/yellow trace wire	Engine Bay	N/A	In headliner or under centre console		
Volkswagen	VW Amarok	Behind Rear Seat	Yes	Yes	Yes	7450111	NHWA02H22 (all models)	P/side H/light Pin #8	P/side H/light Pin #6	Instrument Panel Fuse Box Fuse 54/59	P/side taillight black/blue trace	Behind Rear Seat	3501010	In headliner or on rear glass		